



Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
O/S 3-5	AGDEN ROAD	<i>Acer pseudoplatanus</i>	Damage to Surface	Damaging	TR: Replanting, <i>Corylus colurna</i> - Plant in new 800 pit between 3-5, (same as felled tree)	434255.91	385541.63	<i>Corylus colurna</i>	434256.88	385543
O/S 34, (last tree on road before Kenwood Pk Rd)	AGDEN ROAD	<i>Tilia x europea</i>	Damage to Surface	Damaging	TR: Replanting, <i>Corylus colurna</i> - Plant in new 800 pit at end of road just before Kenwood Park Road (same as felled tree)	434214.63	385498.15	<i>Corylus colurna</i>	434214.23	385497.71
At side of 48 Kenwood Park Road, on THORNSETT RD though, 2nd tree from junction	AGDEN ROAD	<i>Tilia x europea</i>	Damage to Surface	Damaging	TR: Replanting, <i>Corylus colurna</i> - Plant in new 800 pit in space between 2 adjacent mature trees (same as felled tree, check map)	434215.66	385513.32	<i>Corylus colurna</i>	434215.89	385513.53